



Repairing Samsung WF361BVBWR ND Error Code

Samsung WF361BVBWR A1 3.6 Cu. Ft. Capacity 8-Cycle High-Efficiency Front-Loading Washer With Internal Water Heater ND error code repair.

Written By: Brandon Johnson



INTRODUCTION

Samsung WF361BVBWR A1 3.6 Cu. Ft. Capacity 8-Cycle High-Efficiency Front-Loading Washer With Internal Water Heater will sometimes get a ND, Not Draining, error code. Here is a guide to help you clear it.

Step 1 — Repairing Samsung WF361BVBWR ND Error Code



- Remove filter from the lower left corner on the front of the washer

Step 2



- Wash debris from filter and reinstall. Once clean the washer should drain properly.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-25 01:58:20 PM.